



## Errata

### NFPA 13

## *Standard for the Installation of Sprinkler Systems*

### 2019 Edition

**Reference:** 6.4.3.1.1

**Errata No:** 13-19-1

The Technical Committee on Sprinkler System Installation Criteria and the Correlating Committee on Automatic Sprinkler Systems notes the following error in the 2019 edition of NFPA 13, *Standard for the Installation of Sprinkler Systems*.

**Note:** Prior to the printing of NFPA 13, this error was noted and incorporated into the standard at the time of issuance.

1. *Correct the typo from an extract from NFPA 24 as shown legislatively below:*

6.4.3.1.1\* Pipe joints shall not be located directly under foundation ~~fittings~~ footings. [NFPA 24: 10.4.3.1.1\*]

Issue Date: July 3, 2018

**(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see [www.nfpa.org/docinfo](http://www.nfpa.org/docinfo))**

Copyright © 2018 All Rights Reserved  
NATIONAL FIRE PROTECTION ASSOCIATION