

Fire Inspection Report Printoff

Business

Business: Jackson Inc

Phone #: Business License #:

50 West Burton Avenue

South Salt Lake UT 84115

Inspection Overview

Robert

Unit:

Inspection Type: Inspection - General Business No Business

License: License

Reason: Scheduled Shift:

Violation Information

Violation Count: 6

Violations

	Violations	
Violation Code	Description	Comments
1008.3.5	Emergency lighting facilities shall be arranged to provide initial illumination that is not less than an average of 1 footcandle (11 lux) and a minimum at any point of 0.1 footcandle(1 lux) measured along the path of egress at floor level. Illumination levels shall be permitted to decline to 0.6 footcandle (6 lux) average and a minimum at any point of 0.06 footcandle (0.6 lux) at the end of the emergency lighting time duration. A maximum-to-minimum illumination uniformity ratio of 40 to 1 shall not be exceeded. In Group I-2 occupancies, failure of a single lamp in a luminaire shall not reduce the illumination level to less than 0.2 foot-candle (2.2 lux).	Emergency lighting shall be installed within the office
906.2	Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10. Exceptions:	Minimum classification of 2A10B for fire extinguisher
	 The distance of travel to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every 3 years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met: 	Shall be mounted at a height not exceeding five feet from the ground
	2.1.Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed. 2.2.Loss of power or circuit continuity to the electronic monitoring device shall initiate a	

- 2.2.Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.
- 2.3.The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.
- 2.4.Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.
- 2.5.A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.
- 3.In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.

1013.3	Exit signs shall be internally or externally illuminated. Exception: Tactile signs required by Section 1013.4 need not be provided with illumination.	Internally Illuminated Exit Sign shall be installed .
1031.5	Where a door is adjacent to, constructed similar to and can be confused with a means of egress door, that door shall be identified with an approved sign that identifies the room name or use of the room.	Stairway door leading to the subbasement apartment shall be labeled as "Not an Exit", and shall be locked.
904.1	Automatic fire-extinguishing systems, other than automatic sprinkler systems, shall be designed, installed, inspected, tested and maintained in accordance with the provisions of this section and the applicable referenced standards.	The stove in the kitchen shall have an automatic fire suppression system and kitchen hood. (Cooking grease laden vapors)
907.5	A fire alarm system shall annunciate at the fire alarm control unit and shall initiate occupant notification upon activation, in accordance with Sections 907.5.1 through 907.5.2.3.3. Where a fire alarm system is required by another section of this code, it shall be activated by: 1.Automatic fire detectors. 2.Automatic sprinkler system waterflow devices. 3.Manual fire alarm boxes. 4.Automatic fire-extinguishing systems. Exception: Where notification systems are allowed elsewhere in Section 907 to annunciate	The requirement of automatic fire extinguishing system for the stove shall require occupant notification within the space.
	at a constantly attended location.	

Notes:

Signatures Signatures								
<u>Signatures</u>								
Туре	First Name	Last Name	Signature Date	Signature Graphic				
Inspector	Robert	Mathes	08/10/2022					