



Errata

NFPA 101[®]

Life Safety Code[®]

2018 Edition

Reference: 23.7.5

Errata No: 101-18-1

The Technical Committee on Detention and Correctional Occupancies and the Correlating Committee on Safety to Life notes the following error in the 2018 edition of NFPA 101[®], *Life Safety Code*[®].

1. Add paragraph 23.7.5, which was inadvertently replaced/removed from the document, to read as follows:

23.7.5 Keys. All keys necessary for unlocking doors installed in a means of egress shall be individually identified by both touch and sight.

Issue Date: May 30, 2017

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/docinfo)

Copyright © 2017 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION